



CORED HOLE

DETAIL VIEW OF CORED HOLE IN INSULATION WITHOUT SENSOR

SENSOR INDICATOR

FACTORY INSTALLED SEAM TAPE

SINGLE PLY ROOF PRIMER

INSTALLED SENSOR BELOW ROOF MEMBRANE

SINGLE PLY ROOF MEMBRANE

HD COVERBOARD

INSULATION

DECK SUBSTRATE

VAPOUR BARRIER

*Patent Pending*

Title  
**Sensor Installed In New Roofing In Insulation And Coverboard Installed**

DWG No.

Rev. 1.0 Date of issue FEB 14/23

Sheet 1/1

NO-PUNCTURE ROOF DIAGNOSTICS INC