



DETAIL VIEW OF CORED HOLE IN INSULATION WITHOUT SENSOR

CORED HOLE

SENSOR INDICATOR

FACTORY INSTALLED SEAM TAPE

SINGLE PLY ROOF PRIMER

INSTALLED SENSOR BELOW ROOF MEMBRANE

SINGLE PLY ROOF MEMBRANE

HD COVERBOARD

OLD ROOF MEMBRANE

INSULATION

DECK SUBSTRATE

VAPOUR BARRIER

Title  
**Sensor Installed In Re-Cover Roof System**

DWG No.

Rev.

Date of issue

Sheet

NO-PUNCTURE ROOF DIAGNOSTICS INC

1.0

FEB 14/23

1/1